WWW.HSE-JOINING.EU OR SCAN IT HERE





DEVELOPMENT OF HSE-TRAINING TOOLS FOR JOINING

HAZARDS JOINING PROFESSIONALS ARE EXPOSED TO



HOT MATERIALS AND SPATTER



CONFINED SPACES




TOXIC FUMES



GAS CYLINDER



INFRARED AND ULTRAVIOLET RADIATION



VIBRATION



ELECTRICITY



WASTE DISPOSAL



CUTTING



ERGONOMIC



ELECTROMAGNETIC FIELDS



NOISE



PICKLING OF STAINLESS STEEL



USAGE OF Cu FILLINGS WHEN BRAZING AND SOLDERING



OF MATERIAL

RISKS FOR WELDING PERSONNEL



RESULTS PRODUCED IN THIS PROJECT





TRAINING MATERIALS





THIS PROJECT FOCUSES ON PROVIDING MORE INFORMATION AND TRAINING TOOLS ON HEALTH, SAFETY AND ENVIRONMENT IN JOINING



















